

### **ABSTRACT**

To regulate the gloss on a print material, and avoid excess release oil, the properties of the fusing medium are measured, and the gloss on the print material is determined on the basis of the measured properties of the fusing  
5 medium.